

IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN: _____

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2021 model year Chevrolet Tahoe and GMC Yukon vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

| | IMPORTANT Your vehicle is involved in GM safety recall N212340970. Schedule an appointment with your GM dealer. This service will be performed for you at no charge. | |
|--|--|--|
| Why is your vehicle being recalled? | Dealer service technicians programmed these vehicles' brake system control modules (BSCM) with incorrect calibrations. This condition adversely impacts the operation or sensitivity of certain vehicle systems, including electronic stability control, traction control, and anti-lock braking, or cause the loss of trailer braking while towing, increasing the risk of a crash. | |
| What will we do? | Your GM dealer will reprogram the brake system control module with the correct software and calibration data files free of charge. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 25 minutes. | |
| What should you do? | You should contact your GM dealer to arrange a service appointment as soon as possible. | |
| Do you have questions? | If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below. | |

| Division | Number | Text Telephones (TTY) |
|-----------------------|----------------|-----------------------|
| Chevrolet | 1-800-630-2438 | 1-800-833-2438 |
| GMC | 1-866-996-9463 | 1-800-462-8583 |
| Puerto Rico – English | 1-800-496-9992 | |
| Puerto Rico – Español | 1-800-496-9993 | |
| Virgin Islands | 1-800-496-9994 | |

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 21V579.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Regina A. Carto Vice President Global Product Safety and Systems

GM Recall: N212340970