OMB Control No.: 2127-0004

Recall Quarterly Report

21V-585

Manufacturer Name: Mitsubishi Fuso Truck of America, Inc. **NHTSA Recall No. / MFR Recall No.:** 21V-585 /C10120 **Recall Subject:** Front Leaf Spring Shackle Bolts May Be Loose

Owner Notification Beginning Date: OCT 20, 2021

Owner Notification End Date: OCT 20, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 01, 2022	2022-1	952	470	0	1
1	JAN 05, 2022	2021-4	952	282	0	1

This Document Last Updated: APR 07, 2022

Definitions:

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.