OMB Control No.: 2127-0004

Recall Quarterly Report

21V-587

Manufacturer Name : Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 21V-587 /WRG-21

Recall Subject: Fuel Pump May Fail

Owner Notification Beginning Date : SEP 24, 2021

Owner Notification End Date: OCT 25, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JUL 25, 2022	2022-2	175,968	139,263	1,456	1,213
3	APR 28, 2022	2022-1	175,968	129,010	1,844	1,254
2	JAN 27, 2022	2021-4	175,968	101,983	0	1,262
1	OCT 29, 2021	2021-3	175,968	25,965	0	1,107

This Document Last Updated: JUL 28, 2022

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.