## **Recall Quarterly Report**

21V-605

Manufacturer Name : Bentley Motors, Inc. NHTSA Recall No. / MFR Recall No. : 21V-605 /RE21/31 (RC13) Recall Subject : Seat Belt Locking Retractor Malfunction/FMVSS 208 Owner Notification Beginning Date : SEP 30, 2021 Owner Notification End Date: SEP 30, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 22, 2022	2022-1	33	18	1	0
2	JAN 26, 2022	2021-4	33	14	1	0
1	OCT 12, 2021	2021-3	33	0	1	0

This Document Last Updated : APR 26, 2022

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.