

U.S. Department of Transportation

National Highway Traffic Safety Administration

August 6, 2021

Ms. Liz Jones
NEF-107KL
Tiffin Motorhomes, Inc.
105 2nd Street NW
NEF-107KL
21V-610

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Frame Rail Hitch Extensions May Fail

Dear Ms. Jones:

Red Bay, AL 35582

This letter serves to acknowledge Tiffin Motorhomes, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TIFFIN/WAYFARER/2017-2022

Mfr's Report Date: August 5, 2021

NHTSA Campaign Number: 21V-610

Components:

TRAILER HITCHES

Potential Number of Units Affected: TBD

Problem Description:

Tiffin Motorhomes, Inc. (Tiffin) is recalling certain 2017-2022 Wayfarer motorhomes. Continuous stress on the frame rail hitch extensions may cause them to fail.

Consequence:

Extension failure can cause the hitch to detach from the motorhome, increasing the risk of a crash.

Remedy

The remedy is still under development. Owner notification letters are expected to be mail October 4, 2021. Owners may contact Tiffin customer service at 1-256-356-8661. Tiffin's number for this recall is WAY-101.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

The total number of products potentially containing the defect or noncompliance (49 CFR 573.6 (c)(3)).

AMENDED 573 REQUIRED.



The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Tiffin Motorhomes, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

