

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER																									
Safety Recall 97FR	Safety Recall	97FR	What vehicles are included in Safety Recall 97FR?	<table border="1"> <thead> <tr> <th>Country</th> <th>Beginning Model Year</th> <th>Ending Model Year</th> <th>Vehicle</th> <th>Vehicle Count</th> </tr> </thead> <tbody> <tr> <td>USA</td> <td>2021</td> <td>2021</td> <td>ATLAS</td> <td>9</td> </tr> <tr> <td>USA</td> <td>2021</td> <td>2021</td> <td>ATLAS CROSS SPORT</td> <td>24</td> </tr> <tr> <td>CAN</td> <td>2021</td> <td>2021</td> <td>ATLAS</td> <td>12</td> </tr> <tr> <td>CAN</td> <td>2021</td> <td>2021</td> <td>ATLAS CROSS SPORT</td> <td>2</td> </tr> </tbody> </table>	Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count	USA	2021	2021	ATLAS	9	USA	2021	2021	ATLAS CROSS SPORT	24	CAN	2021	2021	ATLAS	12	CAN	2021	2021	ATLAS CROSS SPORT	2
				Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count																					
				USA	2021	2021	ATLAS	9																					
				USA	2021	2021	ATLAS CROSS SPORT	24																					
				CAN	2021	2021	ATLAS	12																					
CAN	2021	2021	ATLAS CROSS SPORT	2																									
			What is the safety concern for Safety Recall 97FR?	Relays in the engine compartment fuse box may have been pre-damaged. Damage to the relay may cause a reduced clearance between the electrical contacts of the relay potentially causing inadvertent electrical contact within the relay and unintended operation of the vehicle components, in this case the vehicle horn and/or the engine starter. A starter and/or horn which activates by itself, and is not detected by the customer, may present a risk of fire due to overheating during extended operation.																									
			What is the repair for Safety Recall 97FR?	To correct this defect, your authorized Volkswagen dealer will inspect and, if necessary, replace the affected relay(s). This work will take about an hour to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.																									
			When will the repair for Safety Recall 97FR be available?	Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit <a href="http://www.vw.com/find-a-dealer">www.vw.com/find-a-dealer</a> .																									