OMB Control No.: 2127-0004

Recall Quarterly Report

21V-618

Manufacturer Name: Custom Fire Apparatus, Inc.

NHTSA Recall No. / MFR Recall No. : 21V-618 /21V-252

Recall Subject: Broken Shaft Seal May Cause Loss of Power Steering

Owner Notification Beginning Date: JUL 12, 2021

Owner Notification End Date: JUL 12, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 26, 2022	2021-4	8	8	0	0
1	DEC 28, 2021	2021-3	8	0	0	0

This Document Last Updated: APR 26, 2022

Definitions:

 $Report\ Quarter:\ The\ quarter\ the\ manufacturer\ is\ reporting\ recall\ completion\ figures\ (e.g.\ 2012-3\ means\ the\ 3^{\bf rd}\ quarter\ of\ 2012).$

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.