

**Recall Quarterly Report****21V-639**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 21V-639 /2021080019  
**Recall Subject :** Air Bag Control Unit Software Malfunction  
**Owner Notification Beginning Date :** SEP 17, 2021  
**Owner Notification End Date:** SEP 17, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 10, 2022	2021-4	66	41	0	0
1	OCT 13, 2021	2021-3	66	19	0	0

This Document Last Updated : JAN 19, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.