



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 1, 2021

Mr. Greg Wallman
President
Space Craft MFG
28115 Old Hwy 40
PO Box 946
Concordia, MO 64021

NEF-107KL
21V-662

Subject: Window Adhesive Failure

Dear Mr. Greg Wallman:

This letter serves to acknowledge Space Craft MFG's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SPACE CRAFT/FIFTH WHEEL/2019-2020
SPACE CRAFT/SEMI TRAILER/2019-2020
SPACE CRAFT/TRAVEL TRAILER/2019-2020

Mfr's Report Date: August 26, 2021

NHTSA Campaign Number: 21V-662

Components:

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER
STRUCTURE

Potential Number of Units Affected: 11

Problem Description:

Space Craft MFG (Space Craft) is recalling certain 2019-2021 travel, fifth-wheel, and semi-trailers (see recall report for specific model numbers). The adhesive that bonds the vented portion of the window may fail.

Consequence:

Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury.

Remedy:

Space Craft will inspect the windows, and replace the vent if necessary, free of charge. Owner notification letters are expected to be mailed in September 2021. Owners may contact Space Craft customer service at 1-660-463-7520.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Space Craft MFG's contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement