

**Recall Quarterly Report****21V-679****Manufacturer Name :** Porsche Cars North America, Inc.**NHTSA Recall No. / MFR Recall No. :** 21V-679 /AMB7**Recall Subject :** Rear Axle Carrier Side May Fracture**Owner Notification Beginning Date :** JAN 06, 2022**Owner Notification End Date:** JAN 06, 2022

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 18, 2022	2022-1	4,934	1,218	0	0

This Document Last Updated : APR 20, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.