## **Recall Quarterly Report**

21V-681

Manufacturer Name : Indian Motorcycle Company NHTSA Recall No. / MFR Recall No. : 21V-681 /I-21-03 Recall Subject : Possible Loss Of Brake Lights From ECU Update Owner Notification Beginning Date : SEP 27, 2021 Owner Notification End Date: SEP 27, 2021



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 3        | APR 13, 2022    | 2022-1            | 177                  | 35                | 0                    | 0                |
| 2        | JAN 19, 2022    | 2021-4            | 177                  | 31                | 0                    | 0                |
| 1        | OCT 27, 2021    | 2021-3            | 177                  | 14                | 0                    | 0                |

This Document Last Updated : APR 15, 2022

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.