## **Recall Quarterly Report**

21V-684

Manufacturer Name : Mack Trucks, Inc. NHTSA Recall No. / MFR Recall No. : 21V-684 /SC0429 Recall Subject : Brake Pedal Cotter Pin Not Installed Properly Owner Notification Beginning Date : SEP 13, 2021 Owner Notification End Date: SEP 20, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 07, 2022	2022-1	2,823	2,700	0	0
2	JAN 04, 2022	2021-4	2,823	2,640	0	0
1	OCT 07, 2021	2021-3	2,823	1,640	0	0

This Document Last Updated : APR 07, 2022

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.