## **Recall Quarterly Report**

21V-768

Manufacturer Name : Honda (American Honda Motor Co.) NHTSA Recall No. / MFR Recall No. : 21V-768 /HBL Recall Subject : Pinhole in Tire Sidewall / FMVSS 139 Owner Notification Beginning Date : NOV 24, 2021 Owner Notification End Date: NOV 24, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 21, 2022	2022-1	181	89	0	0
1	JAN 13, 2022	2021-4	181	70	0	0

This Document Last Updated : APR 26, 2022

## **Definitions** :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7