OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-775

Manufacturer Name: Peach Cargo LLC
Submission Date: DEC 03, 2021
NHTSA Recall No.: 21V-775
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Peach Cargo LLC

Address: 230 Talley St

Adel GA 31620-1947

Company phone: 8961646

Population:

Number of potentially involved: 457 Estimated percentage with defect: 6 %

Vehicle Information:

Vehicle 1: 2021-2022 Peach Cargo PC46SA

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: This notice covers all trailers manufactured by Peach Cargo that are equipped with

axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 3 units of this PC46SA Model from 2021-2022 Model Years and

Peach Cargo Make.

Production Dates: MAR 30, 2021 - JUL 12, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2021-2021 Peach Cargo PC510SA

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information : This notice covers all trailers manufactured by Peach Cargo that are equipped with

axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 1 unit of this PC510SA Model from 2021 Model Year and Peach

Cargo Make.

Production Dates: MAR 30, 2021 - JUL 12, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3 : Vehicle Type : Body Style : Power Train :		h Cargo PC58S	A		
Descriptive Information :	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 31 units of this PC58SA Model from 2021-2022 Model Years and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
Vehicle 4: Vehicle Type: Body Style: Power Train: Descriptive Information:	NR This notice cove axles supplied by	rs all trailers m y Terran Axle L s 17 units of th	anufact LC that	are being recalled un	that are equipped with nder Recall No. 21E067. 1-2022 Model Years and
Production Dates :	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:		NR	End:	NR	☐ Not sequential
Vehicle 5: Vehicle Type: Body Style: Power Train: Descriptive Information:	NR This notice cove axles supplied by	rs all trailers m y Terran Axle L	anufact LC that	are being recalled un	nder Recall No. 21E067.
	This recall cover Peach Cargo Mal		is PC61	2SA Model from 202	1-2022 Model Years and
Production Dates :	O				
VIN Range 1:		NR	End:	NR	☐ Not sequential
Vehicle 6: Vehicle Type: Body Style: Power Train: Descriptive Information:	NR This notice cove	rs all trailers m	anufact	v o	
n 1 =	This recall cover Peach Cargo Mal	rs 23 units of th ke.			nder Recall No. 21E067. 1-2022 Model Years and
Production Dates:			E. 1	ND	□ N. / / / 1
VIN Range 1:	Begin:	NR	End:	NK	☐ Not sequential

Vehicle 7:	2021-2021 Peac	h Cargo PC614	SA		
Vehicle Type :		o .			
Body Style :					
Power Train :	NR				
Descriptive Information :	This notice cove	rs all trailers m	anufact	tured by Peach Cargo that	are equipped with
				are being recalled under I	
	This recall cover Cargo Make.	rs 2 units of this	S PC614	SA Model from 2021 Mode	el Year and Peach
Duadwatian Datas	o .	III 19 9091			
Production Dates:		NR	End:	ND	☐ Not sequential
VIN Range 1:	begin:	INK	Ella .	INK	☐ Not sequential
Vehicle 8:	2021-2022 Peac	h Cargo PC614	ΤА		
Vehicle Type :		8			
Body Style :					
Power Train :	NR				
Descriptive Information :	This notice cover	rs all trailers m	anufact	tured by Peach Cargo that	are equipped with
•	axles supplied by	y Terran Axle L	LC that	are being recalled under F	Recall No. 21E067.
			PC614	TA Model from 2021-2022	2 Model Years and
	Peach Cargo Mal				
Production Dates :					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
Vehicle 9:	2021-2021 Peac	h Cargo PC68S	A		
Vehicle Type :		8			
Body Style :					
Power Train:	NR				
Descriptive Information :	This notice cove	rs all trailers m	anufact	tured by Peach Cargo that	are equipped with
				are being recalled under I	
	This recall cover			Model from 2021 Model	
	Make.				
Production Dates :					
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
Vehicle 10 ·	2021-2021 Peac	h Cargo PC710	SA		
Vehicle Type :		ii cargo i ci io	J11		
Body Style :	1101111111				
Power Train :	NR				
		rs all trailers m	anufact	tured by Peach Cargo that	are equipped with
Descriptive information.				are being recalled under F	
	This recall cover			SA Model from 2021 Model	
	Cargo Make.				
Production Dates :					
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential

Vehicle 11 : Vehicle Type : Body Style : Power Train :		h Cargo PC712	SA			
Descriptive Information :	axles supplied by This recall cover	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 9 units of this PC712SA Model from 2020-2021 Model Years and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021				
VIN Range 1:	Begin:	NR	End:	NR	\square Not sequential	
Vehicle Type : Body Style : Power Train :	NR This notice cove axles supplied by	rs all trailers m y Terran Axle L s 25 units of th	anufact LC that	tured by Peach Cargo that a are being recalled under F 2TA Model from 2020-202	Recall No. 21E067.	
Production Dates :	· ·					
VIN Range 1:		NR	End:	NR	☐ Not sequential	
Vehicle Type : Body Style : Power Train : Descriptive Information : Production Dates :	NR This notice cove axles supplied by This recall cover Peach Cargo Mal MAR 30, 2021 - J	rs all trailers m y Terran Axle L rs 2 units of this ke. IUL 12, 2021	anufact LC that s PC714	tured by Peach Cargo that a are being recalled under F SA Model from 2020-2021	Recall No. 21E067. Model Years and	
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
Vehicle Type : Body Style : Power Train :	NR This notice cove	rs all trailers m	anufact	tured by Peach Cargo that		
	This recall cover Peach Cargo Mal	rs 48 units of th		are being recalled under F 4TA Model from 2020-202		
Production Dates :						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	

Vehicle 15 : Vehicle Type : Body Style : Power Train :		h Cargo PC716'	ГА		
Descriptive Information :	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 61 units of this PC716TA Model from 2020-2021 Model Years and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential
Vehicle Type : Body Style : Power Train :	NR This notice cove axles supplied b	rs all trailers m y Terran Axle L 's 4 units of this	anufact LC that	tured by Peach Cargo that a are being recalled under F TA Model from 2020-2021	Recall No. 21E067.
Production Dates :	· ·				
VIN Range 1:		NR	End:	NR	☐ Not sequential
Vehicle 17:	2022-2022 Peac	h Cargo PC851	2TA		
Vehicle Type :	TRAILERS				
Body Style :					
Power Train :	NR				
Descriptive Information :	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 1 unit of this PC8512TA Model from 2022 Model Year and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
Vehicle 18 : Vehicle Type : Body Style :	2021-2022 Peac TRAILERS	h Cargo PC851	4TA		
Power Train :	NR.				
		re all trailare m	anufact	tured by Peach Cargo that	aro oguinnod with
Descriptive information.	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 2 units of this PC8514TA Model from 2021-2022 Model Years and Peach Cargo Make.				
Production Dates :	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential

	2021-2022 Peac	h Cargo PC851	6TA		
Vehicle Type :					
Body Style :					
Power Train :	NR				
Descriptive Information :	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 8 units of this PC8516TA Model from 2020-2021 Model Years and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
Vahiala 20.	2021 2022 Dage	h Cargo DC951	ОТЛ		
Vehicle Type :	2021-2022 Peac	ii cargo i cooi	OIA		
Body Style :	IKAILEKS				
Power Train :	NR				
		na all trailana m	anufact	tuned by Deech Congo the	t are equipped with
Descriptive Information :	axles supplied by	y Terran Axle L rs 13 units of th	LC that	are being recalled under 18TA Model from 2020-	r Recall No. 21E067.
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
Vahiela 21 ·	2021-2022 Peac	h Cargo PC859	በፐለ		
Vehicle Type :		ii cargo i cosz	UIA		
Body Style:					
Power Train :					
Descriptive Information :		re all trailare m	anufact	tured by Deach Cargo the	it are equipped with
Descriptive information.	axles supplied by	y Terran Axle L rs 55 units of th	LC that	are being recalled under 2020-	r Recall No. 21E067.
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
Vehicle 22:	2021-2021 Peac	h Cargo PC852	2TA		
Vehicle Type :		041801 0002	~		
Body Style :					
Power Train:					
Descriptive Information :		rs all trailers m	anufact	tured by Peach Cargo tha	it are equipped with
Descriptive information.	axles supplied by	y Terran Axle L	LC that	are being recalled under	r Recall No. 21E067.
Production Dates :	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential

Vehicle 23 : Vehicle Type : Body Style : Power Train :		h Cargo PC852	4TA		
Descriptive Information :	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 54 units of this PC8524TA Model from 2020-2021 Model Years and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
Vehicle 24: Vehicle Type: Body Style: Power Train: Descriptive Information:	NR This notice cove axles supplied by	rs all trailers m y Terran Axle L	anufact LC that	are being recalled	go that are equipped with under Recall No. 21E067. 021 Model Year and Peach
Production Dates :	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential
Vehicle 25 : Vehicle Type : Body Style : Power Train : Descriptive Information :	NR This notice cove	rs all trailers m	anufact		
	This recall cover Cargo Make.	s 1 unit of this			under Recall No. 21E067. 22 Model Year and Peach
Production Dates :					
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential
Vehicle 26 : Vehicle Type : Body Style : Power Train :		h Cargo PC852	8TA		
Descriptive Information :	: This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 10 units of this PC8528TA Model from 2020-2021 Model Years and Peach Cargo Make.				
Production Dates :	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential

Vehicle 27 : Vehicle Type : Body Style : Power Train :		h Cargo PC853	0ТА		
Descriptive Information :	This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 3 units of this PC8530TA Model from 2020-2021 Model Years and Peach Cargo Make.				
Production Dates:	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
Vehicle 28: Vehicle Type: Body Style: Power Train: Descriptive Information:	NR This notice cove axles supplied by	rs all trailers m y Terran Axle L	anufact LC that	tured by Peach Cargo that are being recalled under OTTA Model from 2021 Mo	Recall No. 21E067.
Production Dates :	· ·	UL 12, 2021			
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential
Vehicle 29 : Vehicle Type : Body Style : Power Train : Descriptive Information :	NR This notice cove axles supplied by	rs all trailers m y Terran Axle L	anufact LC that	are being recalled under	Recall No. 21E067.
	This recall cover Peach Cargo Mal		PC853	2TA Model from 2020-20	21 Model Years and
Production Dates :	O				
VIN Range 1:		NR	End:	NR	☐ Not sequential
Vehicle 30 : Vehicle Type : Body Style : Power Train :		h Cargo PC853	2ТТА		
Descriptive Information :	: This notice covers all trailers manufactured by Peach Cargo that are equipped with axles supplied by Terran Axle LLC that are being recalled under Recall No. 21E067. This recall covers 1 unit of this PC8532TTA Model from 2021 Model Year and Peach Cargo Make.				
Production Dates :	MAR 30, 2021 - J	UL 12, 2021			
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential

Not sequential

Vehicle 31:	2021-2022 Pe	each Cargo P	C8534TTA			
Vehicle Type :	TRAILERS					
Body Style :						
Power Train :	NR					
Descriptive Information :	axles supplied	l by Terran A vers 23 units	Axle LLC that are being	each Cargo that are equipped with recalled under Recall No. 21E067. odel from 2020-2021 Model Years		
Production Dates:	MAR 30, 2021	-JUL 12, 20	21			
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential		
Vehicle 32 : Vehicle Type : Body Style : Power Train :		each Cargo P	CG8540TTA			
Descriptive Information :	axles supplied	l by Terran A	Axle LLC that are being	each Cargo that are equipped with recalled under Recall No. 21E067. del from 2021 Model Year and Peach		

Description of Defect:

Description of the Defect: According to the axle supplier, Terran Axle LLC, "[i]n the assembly of certain

axles, a certain number of spindle nuts were not torqued to prescribed standards resulting in insufficiently torqued (loose) spindle nuts." See Recall

End: NR

No. 21E067.

Cargo Make.
Production Dates: MAR 30, 2021 - JUL 12, 2021

FMVSS 1: NR FMVSS 2: NR

VIN Range 1: Begin:

Description of the Safety Risk: According to the axle supplier, Terran Axle LLC, "insufficiently torqued

NR

spindle nuts may lead to higher than normal axle

vibration possibly resulting in overheated bearings and bearing failure as well as potential smoking of the axle from friction and improper tire wear and wheel performance. Axle, tire or wheel failure may affect vehicle stability or

control, increasing the risk of a crash."

Description of the Cause: According to Terran Axle, this issue was caused by "[I]mproper torquing of

spindle nut to prescribed levels.'

Identification of Any Warning Terran Axle has advised that this condition may develop without warning.

that can Occur:

Involved Components:

Component Name 1: Spindle Nut

Component Description: Spindle Nut (retains the hub assembly to the spindle)

Component Part Number: 020401

Supplier Identification:

Component Manufacturer

Name: Terran Axle LLC

Address: 1 Westbrook Corporate Center

Suite 300 Westchester Illinois 60154

Country: United States

Chronology:

On or about August 2, 2021, Peach Cargo was notified that Terran Axle LLC was conducting a recall of certain axles that were supplied to Peach Cargo. (Recall No. 21E067) Peach Cargo initiated an inquiry to determine the scope of the issue and to reconcile the list of affected axles against Peach Cargo's manufacturing records to identify potentially affected trailers.

Although Peach Cargo has not made an independent safety defect determination, it is filing this defect information report in response to Terran Axle's defect determination in Recall No. 21E067.

Peach Cargo has not received any reports of accidents or injuries related to the condition described in Terran Axle's notification.

Description of Remedy:

Description of Remedy Program: As described in Terran Axle's Part 573 Defect Information Report, "Terran Axle will notify all trailer manufacture customers, their dealers, and purchasers of trailers incorporating the axles subject to the inspection to determine whether spindle nuts are properly torqued. We mandate manual inspection of each spindle nut assembly (2 per axle) to ensure proper torqueing and, in the event that a spindle nut requires torqueing to meet prescribed standards, we provide detailed instructions and, for axles that have been in operation on a moving trailer and experience vibration, we will require the technician to confirm that the bearings have not been impacted and the axle is properly greased. In the event that bearings have been affected, we make provision for replacement of these bearings."

> Pursuant to 49 CFR 577.11(e), Peach Cargo requests that it be exempt from providing notification of a reimbursement plan. Any pre-notification product failure would have been addressed under the manufacturer's limited warranty. Accordingly, no person would be eligible for reimbursement pursuant to 573.13.

How Remedy Component Differs The remedy involves torqueing the spindle nut to the prescribed from Recalled Component: standards which facilitates proper operability of the axle and consequent wheel and tire function.

Identify How/When Recall Condition Terran Axle advises that it inspected each trailer axle and, if a spindle nut was Corrected in Production: was insufficiently torqued, the spindle nut was torqued to the prescribed standards.

Recall Schedule:

Description of Recall Schedule: Peach Cargo is coordinating owner and dealer notification with Terran

Axle. Peach Cargo has provided dealer and available owner information to Terran Axle, which has commenced the dealer/owner notification

process.

Planned Dealer Notification Date: OCT 11, 2021 - OCT 15, 2021 Planned Owner Notification Date: OCT 11, 2021 - OCT 15, 2021

* NR - Not Reported