OMB Control No.: 2127-0004

Recall Quarterly Report

21V-776

Manufacturer Name: Shyft Group

NHTSA Recall No. / MFR Recall No.: 21V-776 /21-22

Recall Subject: Rear Suspension Fasteners Not Tightened Properly

Owner Notification Beginning Date: NOV 16, 2021

Owner Notification End Date: $NOV\ 16,\ 2021$



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 30, 2022	2021-4	660	132	0	2

This Document Last Updated: JAN 31, 2022

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.