OMB Control No.: 2127-0004

Recall Quarterly Report

21V-804

Manufacturer Name: Honda (American Honda Motor Co.)
NHTSA Recall No. / MFR Recall No.: 21V-804 /KM8
Recall Subject: Gearshift Pedal Arm Welded Improperly
Owner Notification Beginning Date: DEC 10, 2021

Owner Notification End Date: DEC 10, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 21, 2022	2022-2	2,181	1,696	0	0
2	APR 21, 2022	2022-1	2,181	1,391	0	0
1	JAN 13, 2022	2021-4	2,181	325	0	0

This Document Last Updated: AUG 11, 2022

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.