

**Recall Quarterly Report****21V-805**

**Manufacturer Name :** Ford Motor Company  
**NHTSA Recall No. / MFR Recall No. :** 21V-805 /21C26  
**Recall Subject :** Front Door Side Impact Sensors Damaged/FMVSS 214  
**Owner Notification Beginning Date :** NOV 03, 2021  
**Owner Notification End Date:** NOV 03, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 26, 2022	2022-1	777	316	18	0
1	JAN 23, 2022	2021-4	777	195	17	0

This Document Last Updated : MAY 02, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.