

Recall Quarterly Report**21V-813****Manufacturer Name :** Trail King Industries, Inc.**NHTSA Recall No. / MFR Recall No. :** 21V-813 /TK202105**Recall Subject :** Cracked Suspension Beams May Loosen or Detach**Owner Notification Beginning Date :** NOV 12, 2021**Owner Notification End Date:** DEC 06, 2021

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 13, 2022	2022-1	209	43	0	0
1	JAN 19, 2022	2021-4	209	32	0	0

This Document Last Updated : APR 14, 2022

Definitions :Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.