## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-843

Manufacturer Name: Mercedes-Benz USA, LLC

**NHTSA Recall No. / MFR Recall No.:** 21V-843 /2022010002

**Recall Subject :** ECU Software May Cause Engine Stall **Owner Notification Beginning Date :** JAN 28, 2022

**Owner Notification End Date: JAN 28, 2022** 



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 13, 2022	2022-3	8,669	7,494	0	0
2	JUL 10, 2022	2022-2	8,669	6,307	0	0
1	APR 11, 2022	2022-1	8,669	4,427	0	0

This Document Last Updated: OCT 14, 2022

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.