Recall Quarterly Report

21V-856

Manufacturer Name : Mack Trucks, Inc. NHTSA Recall No. / MFR Recall No. : 21V-856 /SC0432 Recall Subject : Broken Shaft Seal May Cause Loss of Power Steering Owner Notification Beginning Date : DEC 10, 2021 Owner Notification End Date: DEC 10, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 04, 2022	2021-4	79	5	0	0

This Document Last Updated : JAN 05, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.