



IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACX-2106
NHTSA RECALL NO. 21V867**

March 2022

TO: U.S. Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect, which relates to motor vehicle safety, exists in 947, 2019-2022 model year Xpeditor chassis manufactured between September 4, 2018, and July 19, 2021, with non-sequential serial numbers between 228021 and 237239, accordingly, a recall to address this issue is being initiated effective March 17, 2022.

MODELS Autocar Xpeditor MY 2019-2021
AFFECTED:

COMPONENTS The hazard lamps may not function with the engine off.
AFFECTED:

SAFETY Non-compliance as the hazard lighting is disabled with the ignition, increasing the
DEFECTS AND risk of personal injury, property damage or a crash.
POTENTIAL
RISKS:

REPAIR The hazard lighting will be reprogrammed at no charge to the owner.
REQUIRED:

REPAIR VIN profiles in the Autocar Warranty System will be updated to show the open recall on
AVAILABLE: March 17, 2022, and a spreadsheet of the affected VINs will be available in the Warranty system.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000