

Recall Quarterly Report**21V-868**

Manufacturer Name : Tesla, Inc.
NHTSA Recall No. / MFR Recall No. : 21V-868 /SB-21-20-007
Recall Subject : Driver's Air Bag Cushion May Tear
Owner Notification Beginning Date : JAN 07, 2022
Owner Notification End Date: JAN 07, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 29, 2022	2022-4	7,600	5,075	0	0
3	JUL 26, 2022	2022-3	7,600	4,444	0	0
2	APR 29, 2022	2022-2	7,600	3,222	0	0
1	JAN 31, 2022	2022-1	7,600	752	0	0

This Document Last Updated : NOV 04, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.