## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-872

Manufacturer Name: Maserati North America, Inc. NHTSA Recall No. / MFR Recall No.: 21V-872 /442 Recall Subject: Fuel Line Sensor Housing May Leak Owner Notification Beginning Date: DEC 17, 2021

**Owner Notification End Date:** DEC 17, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 07, 2022	2021-4	409	74	0	0

This Document Last Updated: JAN 19, 2022

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.