

Recall Quarterly Report**21V-883**

Manufacturer Name : Timpte, Inc.
NHTSA Recall No. / MFR Recall No. : 21V-883 /
Recall Subject : iABS Securing Screws Improperly Tightened
Owner Notification Beginning Date : DEC 13, 2021
Owner Notification End Date: DEC 15, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 30, 2022	2021-4	67	6	3	3

This Document Last Updated : FEB 02, 2022

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.