



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 7, 2021

Mr. Paul Roberts
Roadtrek Inc.
20 Tyler St.,
Cambridge 11763

NEF-107KL
21V-928

Subject: Incorrect Tire Size on Labels/FMVSS 110

Dear Mr. Roberts:

This letter serves to acknowledge Roadtrek Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ROADTREK/PLAY/2021
ROADTREK/PLAY SLUMBER/2021
ROADTREK/ZION SLUMBER/2021

Mfr's Report Date: November 25, 2021

NHTSA Campaign Number: 21V-928

Components:

EQUIPMENT:OTHER:LABELS
TIRES

Potential Number of Units Affected: 212

Problem Description:

Roadtrek Inc. (Roadtrek) is recalling certain 2021 Play, Play Slumber, and Zion Slumber recreational vehicles. The Federal Placard and Tire Pressure labels state the incorrect tire size. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 110, "Tire Selection and Rims."

Consequence:

Incorrect tire information could result in the wrong tires being installed, possibly affecting vehicle stability and control, and increasing the risk of a crash.

Remedy:

Roadtrek will send owners replacement labels, free of charge. Owner notification letters are expected to be mailed in December 2021. Owners may contact Roadtrek customer service at 1-888-762-3873. Roadtrek's number for this recall 2021-03.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

AMENDED 573 REQUIRED.

The population listed in the vehicle descriptions are different, please clarify what the total population is and remove any incorrect numbers. (49 CFR 573.6 (c)(3)).

AMENDED 573 REQUIRED.

We have received Roadtrek's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Roadtrek Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement