## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-934

Manufacturer Name: Daimler Vans USA, LLC

NHTSA Recall No. / MFR Recall No.: 21V-934 /VS3HECKTRI

Recall Subject: Bolt Fasteners on Rear Step Not Properly Tightened

**Owner Notification Beginning Date : FEB 11, 2022** 

**Owner Notification End Date:** FEB 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 05, 2022	2022-3	30	8	0	0
2	JUL 21, 2022	2022-2	30	4	0	0
1	APR 21, 2022	2022-1	30	1	0	0

This Document Last Updated: OCT 12, 2022

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.