

Recall Quarterly Report**21V-955**

Manufacturer Name : Subaru of America, Inc.
NHTSA Recall No. / MFR Recall No. : 21V-955 /WRK-21
Recall Subject : Drive Chain May Break Causing Loss of Drive Power
Owner Notification Beginning Date : AUG 19, 2022
Owner Notification End Date: AUG 19, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	NOV 14, 2022	2022-3	198,255	79,607	0	1,073

This Document Last Updated : NOV 17, 2022

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.