X12 Engines for NHTSA Recall 21E-099:

Francis - Canial Name	\/_b:=l= \\	1 1/2 his da 1 da mai fi a aki an 1 da mai a m (1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1
Engine Serial Number	Vehicle Model	Vehicle Identification Number (VIN)



*** IMPORTANT SAFETY RECALL*** NHTSA Recall No. 21E-099 Cummins Campaign #C2532

INTERIM RECALL NOTIFICATION

Month Day, Year

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain Cummins X12 Engines that were manufactured between April 26, 2016 and November 1, 2021 and for installation in mixer, truck, coach, emergency vehicle, refuse truck, recreational vehicle and crane applications.

This notice applies to the engines(s)/vehicles(s) listed on the enclosed table.

WHAT IS THE PROBLEM?

The fuel tubes between the fuel rail and the injectors for cylinders 4, 5 and 6 may be susceptible to cracking, resulting in a high pressure fuel leak. A high pressure fuel leak in the presence of an ignition source may increase the risk of a fire.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins is currently developing the permanent remedy for this issue. You will receive a second notification to inform you when the final remedy is available and to provide instructions to schedule the recall for your engine.

WHAT SHOULD YOU DO?

In the meantime, Cummins advises you to periodically check the injector fuel tubes for signs of leaking and to seek repairs if leaks are identified. If a leak occurs, the operator may smell diesel fuel or observe a mist.

WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800- CUMMINS (1-800-286-6467), or visit our website at care.cummins.com.



If you have a complaint relative to this recall, you may report it to the following:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Avenue, SE Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

If you have not registered your Cummins product, please complete the enclosed registration card or register your product at https://prodreg.cummins.com/prodreg/#/webform/contactInfo.

If you are no longer the owner of the engines(s) listed on the enclosed table, please forward this notice to the new owner or provide the new owner's contact information to Cummins so that we can notify them of this recall.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

Cummins is taking this action in the interest of your safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator Cummins Inc.