

Equipment Recall

ER22-14

Date Expiration Page 03.2022 N/A 1(3)

First Release.

ENTERTAINER BUSINESS - SEAT BRACKET

DESCRIPTION

Equipment Recall.

NHTSA Recall #22E-004

Applicable vehicles: NONE

Writer: EL <QF7720961 rev8>

ER22-14

Date	Expiration	Page	
03.2022	N/A	2(3)	

defective seat bracket kits to be replaced		new replacement kits	
kit 860351	seat bracket asm, position 1	kit 868187	seat bracket asm, position 1
kit 860355 3a	seat bracket asm, position	kit 868188	seat bracket asm, position 3a

DEFECTIVE BRACKETS




FIGURE 1: KIT 860351 BRACKET POSITION 1 (4 seats)

D	ate	Expiration	Page
0	3.2022	N/A	3(3)




FIGURE 2: Kit 860355 BRACKETS POSITION 3A (1 or 2 seats)

HOW TO IDENTIFY DEFECTIVE BRACKETS

The defective brackets are missing ¼ fillet weld beads as shown on the images below.




Figure 3: item 2




Figure 4: item 1