OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22E-022

Manufacturer Name: Midwest Motorsports LLC

Submission Date: MAR 18, 2022 NHTSA Recall No.: 22E-022

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Midwest Motorsports LLC

Address: 1634 Marion Ave

Grand Haven MI 49456

Company phone: 616-935-7443

Population:

Number of potentially involved : 186 Estimated percentage with defect : 100 %

Equipment Information:

Brand / Trade 1: Kylin

Model: K77
Part No.: K77
Size: XXL
Function: NR

Descriptive Information: This is amount of size XXL helmets in this "lot" produced in September of 2020

Production Dates: SEP 14, 2020 - SEP 28, 2020

Description of Noncompliance:

Description of the The helmet allowed a penetration during testing

Noncompliance:

FMVSS 1: 218 - Motorcycle helmets

FMVSS 2: NR

Description of the Safety Risk: A penetration of the helmet could occur during an accident

Description of the Cause : NR
Identification of Any Warning None

that can Occur:

Involved Components:

Component Name: NR

Component Description: NR

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: YUEQING Motorcycle Fittings Co Ltd

Address: No 100 Haiqiao Rd

Niubidong Yueqing Zhejiang Foreign States 325600

Country: China

Chronology:

A test was performed in April of 2020 at ACT Labs in California

Description of Remedy:

Description of Remedy Program: These helmets cannot be repaired. All the buyers from this lot will be

informed of the recall and requested to return their helmet for a refund

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition This was the last lot of K77 helmets that we purchased.

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: MAY 06, 2022 - MAY 18, 2022

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Part 573 Safety Recall Report

22E-022

Page 3

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573