

Recall Quarterly Report

22E-030

Manufacturer Name : Prevost Car (US) Inc.
NHTSA Recall No. / MFR Recall No. : 22E-030 /SR22-05
Recall Subject : Alternator Belt May Overheat Seized Bearing
Owner Notification Beginning Date : SEP 26, 2022
Owner Notification End Date: APR 25, 2023



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JUL 11, 2023	2023-2	27,652	478	0	0
3	APR 28, 2023	2023-1	27,652	460	0	0
2	JAN 23, 2023	2022-4	16,974	335	0	0
1	OCT 20, 2022	2022-3	16,974	0	0	0

This Document Last Updated : JUL 12, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.