



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 8, 2022

Mohammad Maqbool
CEO
Milwaukee Performance Helmets
34 Owens Dr
Wayne, NJ 07470

NEF-107SS
22E-044

Subject: Helmets May Not Adequately Protect User/FMVSS 218

Dear Mohammad Maqbool:

This letter serves to acknowledge Milwaukee Performance Helmets's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MPH/MOTORCYCLE HELMET/9999

Mfr's Report Date: May 26, 2022

NHTSA Campaign Number: 22E-044

Components:

EQUIPMENT:MOTORCYCLE:HELMETS
EQUIPMENT:OTHER:LABELS

Potential Number of Units Affected: 340

Problem Description:

Milwaukee Performance Helmets (Milwaukee Helmets) is recalling certain size large model MPH9720DOT and size small model MPH9721DOT helmets. The helmets may lack proper retention system integrity, penetration protection, and labels. As such, these helmets fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 218, "Motorcycle Helmets."

Consequence:

A helmet that does not provide adequate protection increases the risk of injury during a crash.

Remedy:

Milwaukee Helmets will offer a refund of the purchase price. Owner notification letters are expected to be mailed July 25, 2022. Owners may contact Milwaukee Helmets customer service at 1-800-990-7423 or Helmet-recall@shafinc.com.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

The estimated dates provided for notifying owners extend beyond 60 days. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Milwaukee Performance Helmets's contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement