

**\*\*\* IMPORTANT SAFETY RECALL \*\*\***  
**NHTSA Recall No. 22E-060**

July 22, 2022

GILLIG LLC  
451 Discovery Drive,  
Livermore, CA 94551

Dear Cummins OEM Customer:

We are writing to inform you that Cummins Inc. has determined that a safety-related defect exists in certain BP74E Battery Packs that were manufactured between August 6, 2020 and May 19, 2022. Cummins has initiated a recall of the subject battery packs. Our records indicate that some of these battery packs have been shipped to you.

A copy of Cummins' initial Part 573 Defect Notification report is enclosed. This notification was submitted to the National Highway Traffic Safety Administration (NHTSA) on July 19, 2022. As more fully described in the Defect Notification, the battery packs may develop internal coolant leaks, possibly leading to gases venting from the battery, smoke or a battery fire.

Enclosed is a list of affected serial numbers for battery part numbers 6301592 and A063V367 that our records indicate were shipped to your plants. For battery packs installed in vehicles that have left your control, we encourage you to make a safety defect determination in accordance with 49 USC 30118 *et seq.* and, as appropriate, to submit a Defect Notification to NHTSA in accordance with 49 CFR Part 573. Cummins will conduct the recall, notify vehicle owners, perform the remedy, and submit quarterly status reports to NHTSA and the OEM. Cummins is requesting that you provide the associated vehicle model identification, VINs and owner contact information to facilitate owner notification. Please work with your Cummins account team leader to ensure that the requested information is provided to Cummins as soon as possible.

As a supplier of original equipment, Cummins has no obligation to submit a defect notification to Transport Canada. However, Cummins does, as a courtesy, notify Transport Canada when Cummins submits a defect notification to NHTSA, advising that some OEMs may have affected vehicles. If you have an obligation to report the defect to Transport Canada, we ask that you please provide us with the Transport Canada recall number assigned to your vehicle recall. Cummins cannot mail owner letters compliant with Transport Canada regulations with respect to your recalled vehicles without the recall number assigned by Transport Canada. Cummins will provide the applicable data to you after our mailings are completed so that you can submit the required notification reports to Transport Canada, as well as provide you the completion rate data so that you can submit the required quarterly completion reports to Transport Canada.

For battery packs that are still in your inventory, please contact Brian Whaley at [brian.j.whaley@cummins.com](mailto:brian.j.whaley@cummins.com) to arrange for repairs. Please note that Federal law prohibits delivery of battery packs, or vehicles equipped with these battery packs, under a sale or lease until this condition has been remedied.

Cummins apologizes for this inconvenience, but we are initiating this action in the interest of our customers' safety and satisfaction with our products. Thank you for your assistance.

Please confirm receipt of this communication.

Sincerely,

[REDACTED]

[REDACTED]

[REDACTED]

Electrified Components-Cummins Inc.  
500 Central Avenue, Columbus, IN, 47201

[REDACTED]

Enclosures:

1. Cummins Part 573 Defect Notification
2. Battery serial number list