OMB Control No.: 2127-0004

Recall Quarterly Report

22V-006

Manufacturer Name: Reading Truck Body, LLC **NHTSA Recall No.** / **MFR Recall No.**: 22V-006 /

Recall Subject : Subframe Rear Pivot Mount Weld May Fail

Owner Notification Beginning Date : JAN 12, 2022

Owner Notification End Date: FEB 25, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	SEP 26, 2022	2022-2	299	135	5	2

This Document Last Updated: SEP 27, 2022

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.