

**Recall Quarterly Report****22V-036**

**Manufacturer Name :** General Motors, LLC  
**NHTSA Recall No. / MFR Recall No. :** 22V-036 /N212351030  
**Recall Subject :** Rear Wheel Driveshaft Assemblies May Fail  
**Owner Notification Beginning Date :** MAR 14, 2022  
**Owner Notification End Date:** MAR 14, 2022



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 3        | OCT 17, 2022    | 2022-3         | 1,789             | 1,122          | 8                 | 0             |
| 2        | JUL 19, 2022    | 2022-2         | 1,789             | 755            | 12                | 0             |
| 1        | APR 22, 2022    | 2022-1         | 1,789             | 15             | 0                 | 0             |

This Document Last Updated : OCT 21, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.