This is a representative letter. Customer letters are personalized and list specific model, model year and VIN.



## **IMPORTANT SAFETY RECALL**

March 2022

This notice applies to your vehicle, VIN: \_\_\_\_\_

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2021 model year Cadillac Escalade and Escalade ESV, Chevrolet Suburban and Tahoe, and GMC Yukon and Yukon XL vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

## IMPORTANT

- Your vehicle is involved in GM recall N212351030, N212351031, or N212351032.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?	The rear-wheel drive-shaft assemblies in these vehicles may have been manufactured by GM's supplier with recirculating balls that were not properly heat treated. The recirculating balls may deform over time, resulting in noise and vibration. With continued use, the affected joint in the drive-shaft assembly could seize and the vehicle could lose propulsion. If the vehicle loses propulsion, there is increased risk of a crash.
What will we do? What should you do?	Your GM dealer will replace the left rear-wheel drive-shaft assembly. This service will be performed for you at <b>no charge</b> . Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 1 hour and 25 minutes. You should contact your GM dealer to arrange a service appointment as soon as possible.

## Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Cadillac	1-866-982-2339	1-800-833-2622
Chevrolet	1-800-630-2438	1-800-833-2438
GMC	1-866-996-9463	1-800-462-8583
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 22V036.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Regina Carto Vice President Global Vehicle Safety and Systems

GM Recall N212351030, N212351031, N212351032