## **Recall Quarterly Report**

22V-047

Manufacturer Name : Seagrave Fire Apparatus, LLC NHTSA Recall No. / MFR Recall No. : 22V-047 / Recall Subject : Rear Axle Drive Pinion May Fracture Owner Notification Beginning Date : FEB 23, 2022 Owner Notification End Date: MAR 02, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 19, 2023	2022-4	7	2	0	0
3	NOV 07, 2022	2022-3	7	2	0	0
2	OCT 27, 2022	2022-2	7	2	0	0
1	SEP 26, 2022	2022-1	7	0	0	0

This Document Last Updated : JAN 19, 2023

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7