OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

Manufacturer Name :Tiffin Motorhomes, Inc.Submission Date :FEB 08, 2022NHTSA Recall No. :22V-055Manufacturer Recall No. :TIF-121

## Manufacturer Information :

Manufacturer Name : Tiffin Motorhomes, Inc. Address : 105 2nd Street NW PO Box 596 Red Bay AL 35582 Company phone : 999

## **Population :**

Number of potentially involved : 247 Estimated percentage with defect : 100 %

🖈 🛝 📩 😡

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

### Vehicle Information :

Vahiela 1 :	2020-2022 Tiffin Allegro Red	
	8	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :	OTHER	
Power Train :	DIESEL	
Descriptive Information :	2020 Allegro Red - 123 2021 Allegro Red - 100 2022 Allegro Red - 24	
Production Dates :	IAN 01, 2020 - DEC 31, 2022	
VIN Range 1:	egin: NR End: NR 🗌 Not	sequential

### **Description of Defect :**

Description of the Defect :	Awning can become detached from sidewall of coach.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Awning could detach, which in turn could cause injury.
Description of the Cause :	Installers were not setting the awning in the correct location, so the screws were not hitting/penetrating the metal backer.
	Visually inspecting the awning during pre-trip inspection or during maintenance inspection could show separation from sidewall and/or looseness.

### **Involved Components :**

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

Component Name 1:	Awning
Component Description :	Covering attached to sidewall of coach that can be unfurled to provide shade or rain protection.
Component Part Number :	NR

### **Supplier Identification :**

#### **Component Manufacturer**

NR

Name : NR

Address : NR

Country: NR

### **Chronology**:

12/17/2021 Tiffin was contacted about an awning bracket detaching on one end of the patio awning on of a 2022 37 PA Allegro Red.

12/20/2021 Tiffin started investigation.

1/25/2022 Determined scope to include only the Allegro Red 37 PA floorplan due to the installation process and location of backers.

1/25/2022 Issue and findings of investigation were brought before Safety Committee members where all members voted to recall the 2020 - 2022 Allegro Red 37 PA motorhomes with sidewall mounted patio awnings.

### **Description of Remedy :**

Description of Remedy Program :	We are currently waiting for work instructions. However, each unit involved will be inspected to see if the awning loose, and if so it will be repaired at no charge to the customer. Details of the reimbursement plan will be included in the owner's notification letter.
5 1	The remedied component will now be audited during production to make sure installation of awning is in correct location and the screws are hitting/penetrating the metal backer. There will also be a second audit at the end of production.
Identify How/When Recall Condition was Corrected in Production :	The first audit during production was put into place 1-10-2022.

The information contained in this report was submitted pursuant to 49 CFR §573

### **Recall Schedule :**

Description of Recall Schedule :	Customer notification will be made by first class mail using Tiffin
	Motorhomes records to determine the names and addresses of involved.
	Repairs will be made at no charge to the customer.
Planned Dealer Notification Date :	APR 01, 2022 - APR 01, 2022
Planned Owner Notification Date :	APR 01, 2022 - APR 01, 2022

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR  $\S573$