

Recall Quarterly Report

22V-078

Manufacturer Name : Mercedes-Benz USA, LLC
NHTSA Recall No. / MFR Recall No. : 22V-078 / 2022030007
Recall Subject : Incorrect Front Driver's Air Bag Module
Owner Notification Beginning Date : MAR 25, 2022
Owner Notification End Date: MAR 25, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 11, 2022	2022-1	50	11	0	0

This Document Last Updated : APR 12, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.