## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

22V-080

Manufacturer Name: Jaguar Land Rover North America, LLC

NHTSA Recall No. / MFR Recall No.: 22V-080 /N664

**Recall Subject :** SRS Warning Light Malfunction

**Owner Notification Beginning Date : MAR 23, 2022** 

**Owner Notification End Date:** MAR 23, 2022



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 3        | OCT 28, 2022    | 2022-3            | 18,824               | 9,949             | 692                  | 0                |
| 2        | JUL 22, 2022    | 2022-2            | 18,824               | 7,091             | 615                  | 0                |
| 1        | APR 29, 2022    | 2022-1            | 18,824               | 1,201             | 0                    | 0                |

This Document Last Updated: OCT 31, 2022

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.