

## IMPORTANT SAFETY RECALL RVXX2201 NHTSA RECALL # 22V-115

### DEAR VOLVO TRUCK OWNER:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Volvo Trucks North America has decided that a defect which relates to motor vehicle safety exists in certain 2022 and 2023 Volvo VN model vehicles manufactured from December 13, 2021 through January 12, 2022.

| SAFETY DEFECT:                   | On certain trucks, there is a potential for sleeper cabinets to pull away<br>from walls, due to bolts may have been installed without necessary<br>washers.   |
|----------------------------------|---|
| SAFETY RISK:                     | In the event of an accident, the sleeper cabinets may pull free from the cab structure and potentially cause injury.  |
| PRECAUTIONS YOU<br>CAN TAKE:     | There are no precautions you can take other than having your vehicle repaired<br>by a Volvo Parts and Service Center.   |
| TIME REQUIRED FOR<br>THE REPAIR: | The time required to repair your vehicle is approximately 1 hour.   |
| WHAT YOU SHOULD<br>DO:           | You should contact the nearest Volvo Parts and Service Center and make an appointment. Dealers will inspect the mounting hardware and install the washer to the existing bolt as needed.at no cost to you.            |
|                                  | You can locate the closest Volvo Parts and Service Center by going on line to <u>http://www.volvo.com/trucks/na/en-us/dealers/</u> and selecting "Dealer Locator" or by calling our toll-free number: (800) 528-6586. |

# **NOTICE REGARDING LEASED VEHICLES:** If you are a Lessor of vehicles subject to this Notice, you have an obligation under Federal Law to provide a copy of this Notice to all Lessees within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the Lessee(s) to whom you send a copy of this letter, the date you send this letter, and the Vehicle Identification Number(s) of the vehicle(s) that you have leased to that lessee. For purposes of this Notice, the term Lessor means: a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles (as defined in CFR Section 577.4), as of the date of notification by the manufacturer of the existence of a safety-related defect or non-compliance with a Federal Motor Vehicle Safety Standard in one or more of the leased motor vehicles.

- **OWNER RECALL RESPONSE CARD:** The enclosed "Notice of Vehicle Recall" identifies your vehicle. If you no longer own the vehicle, please help us update our records by completing the "Vehicle Disposition Record" portion of the enclosed postage-free Notice of Mandatory Safety Campaign card and mailing it back to us.
- ASSISTANCE/If your vehicle has not been repaired within a reasonable time after<br/>delivering it to a Volvo Parts and Service Center, please contact:

Volvo Trucks North America Regulatory Affairs Department, P.O. Box 26115 Greensboro, NC 27402-6115 <u>vtna.regulatoryaffairs@volvo.com</u>

## PRE NOTIFICATION<br/>REMEDIES:If you have previously paid for repairs as a result of this issue, you may be<br/>entitled to recovery of those expenses.Submit copies of all documentation supporting your claim according to<br/>the rules specified in the "General Plan for Reimbursement of Pre-<br/>notification Remedies" provided in this mailing.

We regret any inconvenience this may cause to your operation, but hope you will appreciate our sincere efforts to demonstrate Volvo's commitment to provide our customers with the best possible product.

## VOLVO TRUCKS NORTH AMERICA