

March 4, 2022

Mr. Garett Carolus Keystone RV Company PO Box 2000 Goshen, IN 46527

Subject: Circuit Not Properly Grounded

Dear Mr. Carolus:

This letter serves to acknowledge Keystone RV Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: CROSSROADS/SUNSET/2022

Mfr's Report Date: March 2, 2022

NHTSA Campaign Number: 22V-117

Components: ELECTRICAL SYSTEM

Potential Number of Units Affected: 95

Problem Description:

Keystone RV Company (Keystone) is recalling certain 2022 Crossroads Sunset 330SI travel trailers. The outside receptacle electrical circuit may not be properly protected by a ground-fault circuit interrupter (GFCI).

Consequence:

An unprotected electrical circuit can cause electric shock, increasing the risk of an injury.

Remedy:

Dealers will wire the circuit so that the outside receptacle is protected, free of charge. Owner notification letters are expected to be mailed April 25, 2022. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 22-424.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

We have received Keystone's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107KL 22V-117

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Keystone RV Company's contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alae Andry

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

