## **Recall Quarterly Report**

22V-145

Manufacturer Name : Ford Motor Company NHTSA Recall No. / MFR Recall No. : 22V-145 /22S13 Recall Subject : Improperly Installed Steering Shaft Bolt Owner Notification Beginning Date : APR 01, 2022 Owner Notification End Date: APR 01, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 27, 2022	2022-2	72	40	0	0

This Document Last Updated : AUG 03, 2022

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.