IMPORTANT SAFETY RECALL

KZ RV, L.P.

NHTSA Recall Number 22V-161
Transport Canada Recall Number 2022-120
Internal Recall Number: KZ-2022-01

Date: March 18, 2022

TO: KZ RV Dealer

Problem

The vehicles subject to this recall were built with a defective coupler. This coupler may have missing or incomplete welds which may cause the trailer to separate from the tow vehicle and could result in a crash resulting in property damage, personal injury, or death.

RANGE OF VEHICLES INVOLVED:

- 2022 Connect
- 2022 Sonic
- 2022 SportTrek
- 2022 Stratus

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 1 hour.

SERVICE ACTION:

The repair procedure is to inspect the coupler and if welds are missing to replace the coupler per the included repair instructions.

encl. - Owners Letter

Delbert Miller

Vice President Corporate