

**Recall Quarterly Report****22V-166**

**Manufacturer Name :** Newmar Corporation  
**NHTSA Recall No. / MFR Recall No. :** 22V-166 /  
**Recall Subject :** Bolt On Steering Column Not Tightened Properly  
**Owner Notification Beginning Date :** MAY 16, 2022  
**Owner Notification End Date:** MAY 16, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 19, 2023	2022-4	1,277	829	0	0
2	OCT 24, 2022	2022-3	1,277	644	0	0
1	JUL 21, 2022	2022-2	1,277	296	0	0

This Document Last Updated : JAN 19, 2023

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.