

**Recall Quarterly Report****22V-175****Manufacturer Name :** Arcimoto Inc**NHTSA Recall No. / MFR Recall No. :** 22V-175 /**Recall Subject :** Brake Pressure Switch May Fail**Owner Notification Beginning Date :** MAY 27, 2022**Owner Notification End Date:** JUN 03, 2022

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	NOV 03, 2022	2022-3	541	203	0	4
1	AUG 01, 2022	2022-2	541	0	0	0

This Document Last Updated : NOV 08, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.