

Recall Quarterly Report**22V-182**

Manufacturer Name : Reading Truck Body, LLC
NHTSA Recall No. / MFR Recall No. : 22V-182 /
Recall Subject : PTO Timer Delay Module Incorrectly Mounted
Owner Notification Beginning Date : MAY 13, 2022
Owner Notification End Date: JUL 28, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	NOV 04, 2022	2022-3	187	93	49	4
1	SEP 26, 2022	2022-2	187	84	8	4

This Document Last Updated : NOV 04, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.