

Part 573 Safety Recall Report

22V-199

Manufacturer Name : Heartland Recreational Vehicles, LLC

Submission Date : MAR 29, 2022

NHTSA Recall No. : 22V-199

Manufacturer Recall No. : TBD



Manufacturer Information :

Population :

Manufacturer Name : Heartland Recreational Vehicles, LLC

Number of potentially involved : 26

Address : 1001 All Pro Drive

Estimated percentage with defect : 100 %

Elkhart IN 46514

Company phone : 8772628032

Vehicle Information :

Vehicle 1 : 2021-2022 Heartland North Trail

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The Federal certification label does not have the correct (GAWR) axle rating.

Production Dates : DEC 22, 2020 - FEB 15, 2022

VIN Range 1 : Begin : 5SFNB3125MN461993 **End :** 5SFNB312XNN501020 Not sequential

Description of Noncompliance :

Description of the Noncompliance : Certain North Trail model 26DBS Travel Trailers do not conform to 49 CFR Part 567 – Certification and Federal Motor Vehicle Safety Standard

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : The owner would not know the actual axle weight rating of the unit and it could be overloaded due to incorrect axle listing. This could lead to an increased risk of a crash or personal injury.

Description of the Cause : The information for the GAWR (axle rating) was entered incorrectly into the model table for this model unit. This caused to our printed VIN tags to be incorrect.

Identification of Any Warning NA
that can Occur :

Involved Components :

Component Name 1 : Federal VIN Tag

Component Description : Federal VIN Tag

Component Part Number : na

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

3/16 - engineering caught the discrepancy during a routine audit. 3/17-3/22 finalized scope 3/24 sent to the safety committee

Description of Remedy :

Description of Remedy Program : The manufacturer will send out replacement certification labels. This will be corrected at no expense to the owner. All reimbursements will be covered by Heartland's general reimbursement plan.

How Remedy Component Differs from Recalled Component : The GAWR (axle ratings) will be corrected on the new certification labels.

Identify How/When Recall Condition was Corrected in Production : Heartland corrected the GAWR in the system so the VIN tags will print properly.

Recall Schedule :

Description of Recall Schedule : A mailing will begin once approval is received

Planned Dealer Notification Date : MAY 28, 2022 - MAY 28, 2022

Planned Owner Notification Date : MAY 28, 2022 - MAY 28, 2022

* NR - Not Reported