

Recall Quarterly Report**22V-237**

Manufacturer Name : Prevost Car (US) Inc.
NHTSA Recall No. / MFR Recall No. : 22V-237 /
Recall Subject : Passenger Bench Seat Frame Bolts May Be Loose
Owner Notification Beginning Date : JUN 15, 2022
Owner Notification End Date: JUN 15, 2022



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2 | OCT 20, 2022 | 2022-3 | 155 | 8 | 0 | 0 |
| 1 | SEP 29, 2022 | 2022-2 | 155 | 0 | 0 | 0 |

This Document Last Updated : OCT 24, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.