



---

## **New Safety Recall Advanced Communication – Z36**

FCA US LLC (FCA US) has announced a safety recall on certain 2022 Model Year (MP) Jeep® Compass vehicles.

### **REASON FOR THIS SAFETY RECALL**

Some of the above vehicles may have been built with an off-location weld(s) on the front seat head restraint frames. Head restraints that do not meet the strength requirements may result in an increased risk of injury to seat occupants during certain crashes.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No.202a. S4.1 requires that "a head restraint that conforms to either S4.2 [static strength] or S4.3 [dynamic strength] of this section must be provided at each front outboard designated seating position." Vehicles built with a front seat head restraint frame manufactured with an off-location weld may not meet the FMVSS 202a S4.2 static strength requirements.

### **SERVICE ACTION**

FCA US will conduct a voluntary safety recall to replace both front seat head restraints. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 2nd Quarter of 2022.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations  
FCA US LLC